

Form C

Information Needed to Declare Exemption

National Emission Standards for Hazardous Air Pollutants for Glass Manufacturing Area Sources

40 CFR part 63 subpart SSSSSS
(<http://www.epa.gov/ttn/atw/area/fr26de07.pdf>)

Received
JAN 13 2010
Office Of Air, Waste
And Toxics

1. Business Name: UROBOROS GLASS STUDIOS INC.
2. Owner/Operator Name: ERIC LOVELL
3. Mailing Address: 2139 N. KERBY, PORTLAND OR 97227
4. E-mail Address: eric@uroboros.com
5. Address (physical location) of Source: 2139 N. KERBY, PORTLAND OR 97227
6. Primary SIC and NAICS codes: NAICS: 327212
7. Glass products manufactured: MULTI-COLOR "TIFFANY STYLE" SHEET,
SINGLE COLOR SHEETS, FRITS, BILLETS, STRINGS, RODS

8. Do you use a continuous furnace? ☐ Yes ☒ No

9. Amount of glass produced: 300 tons per year

10. Do you add any of the following compounds to your furnace charge*:

| | | | | | |
|---------|---|-----------|---|----------|---|
| Arsenic | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Cadmium | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Chromium | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Lead | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Manganese | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Nickel | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |

*Note that these metals are typically found in glass formulation additives; contact your supplier if you're unsure.

11. Although I am not currently subject to the Glass Manufacture's NESHAP, I will keep records of furnace types, glass production, and metal HAP compounds used in furnace charges ☒ Yes ☐ No

12. Certification


I certify that, based on information and belief formed after reasonable inquiry, the statements and information in this report and the supporting enclosures are true, accurate and complete.

Print the name of the "Responsible Official*" for the facility:

| | | |
|------------------------------|------------------|---------------------|
| <u>ERIC LOVELL</u> | <u>PRESIDENT</u> | <u>503-284-4900</u> |
| Name of Responsible Official | Title | Phone Number |

*A "Responsible Official" can be:

- The president, vice-president, secretary, or treasurer of the company who owns the facility
- The owner of the facility
- The plant engineer or supervisor
- A government official if the facility is owned by the Federal, State, City, or County government
- A ranking military officer if the facility is located on a military base


Signature of "Responsible Official"

1-11-10
Date

Keep a copy of this form for your records.

Mail the original to:

Region 10 Office of the EPA
Director, Office of Air, Waste and Toxics
1200 6th Ave., Suite 900, OAQ-107
Seattle, WA 98101

Mail or fax a copy to:

Department of Environmental Quality
Attn: Jerry Ebersole
811 SW Sixth Ave
Portland, OR 97204
Fax: 503-229-5675

Received
JAN 13 2016
Office Of Air
And Toxics

UNITED STATES DEPARTMENT OF HEALTH & HUMAN SERVICES
ENVIRONMENTAL PROTECTION AGENCY
OFFICE OF AIR AND TOXICS
WASHINGTON, DC 20460

TO: [illegible]
FROM: [illegible]
SUBJECT: [illegible]

[illegible text block]

[illegible text block]

[illegible text block]

[illegible text block]